


Botron High Quality Calibration units are designed to simplify the process of calibration of the Botron wrist strap tester B8201. With the rotation of the selector switch you can test if your unit is in working order. **Disclaimer.** All statements of technical information are believed to be true and are based upon tests we believe to be reliable. The proper use and application for this product must be the responsibility of the user. The statements herein shall have no force or effect.



PROPERTIES

SPECIFICATIONS

- 750k-10 Megohm
- Low Fail
- Pass
- Pass
- High Fail
- Selector Switch
- Abs plastic case

OPERATION:

Insert two test leads into banana jack on top of Calibration unit. One test lead goes to tester banana jack on front of tester (A) B8201 . Other test lead from top of calibration unit goes to touch plate with alligator clip, clip onto touch plate (B) and push to test. Rotate selector switch to LOW FAIL and push tester B8201, Low Fail light should come on. Repeat test as you rotate to Pass and HIGH FAIL. Test leads are sold separately.

OTHER PRODUCTS:

B8201 Touch plate wrist strap Tester
B8511 Combo tester, wrist & heel
B82450 Combo testers & stand
B82250 Dual tester & stand
B85502 Combo Calibration unit
B8202 Wrist tester
B8525 Deluxe dual test station

RELATED TEST EQUIPMENT:

B8571 Digital / Analog Megger
B8563 Analog Megohm meter
B8530 Constant monitor
B9202 Constant monitor
BSRM-10 10 light surface meter
BSRM-6 6 light surface meter.

BOTRON CO. INC.

325 W. MELINDA LN
 PHOENIX AZ 85027

PH# 623-582-6700 FAX# 623-582-6776

sales@botron.com / www.botron.com

WRIST STRAP CALIBRATION UNIT

S85501